Median Drains Hydraulic Policy

Bill P Schmidt, PE INDOT Hydraulics Team Leader wpschmidt@indot.in.gov

(317) 232-5148



The drainage infrastructure required for areas that separate opposing lanes of traffic or divided roadways that contain trapped flow.





Shoulder Areas with Barrier Walls

- Generally use a H-5 or HA-5 type inlet due to flatter slopes (less than 10:1)
- Concrete or HMA Shoulders
- Spacing usually close



Shoulder Areas with Barrier Walls

- May have slotted drain option (mainly for snow melt against barrier wall)
- Slotted drain option should be used in sags, low side of superelevated curves and every third inlet on grade (IDM 203-4.04(10))





Non-Wall Divided Areas

- Most Common: Recycled Ashphalt Pavement (RAP) or Vegetated
- Will use a P-12 or N-12 type



Type P-12 Inlet



Type N-12 Inlet

Non-Wall Divided Areas

- P-12 and N-12 type inlet has adjustable slope (6:1, 8:1, 10:1)
- The basin can be modified deeper to accommodate larger pipe



Statewide Interstate Added Travel Lanes (ATL)

Recently completed or in progress

• Mostly I-65 & I-69



Statewide Interstate Added Travel Lanes

- Added lanes encroach into the existing median
 - Median loses waterway conveyance area
 - Inside edge of travel lane becomes a lower elevation (2% x 12 ft = 0.24 ft)



Statewide Interstate Added Travel Lanes

• Added lanes encroach into the existing median





- Lack of Redundancy
 - Water will go on or over the roadway if drainage fails
 - The road is the emergency spillway
 - Medians are typically on major corridors and/or divided highways
 - High Traffic Volume (traffic delays, commute times increase)
 - High Travel Speeds (safety)
 - Economy (commerce affected)



- Clogging
 - Flatter inlets at higher risk of clogging
 - Higher traffic volume = more trash
 - Grass clippings from mowers in vegetated medians

• Leaves from nearby forests



• Berms that are higher than roadways







- Poor Design
 - Discharge determination too low
 - Inlet location
 - Lack of consideration of the risks
 - Not following policy or considering other precautions
 - Not maintainable



I-65 South Indy Example

• Local Flooding on April 3, 2018, closes I-65 on the Indy Southside for approximately 3-6 hours initiated by heavy rains during the Tuesday morning commute.

• Note: I-65 added travel lane construction was 2014-2015.



I-65 South Indy Example

• After some time, INDOT Hydraulics called out to investigate. Four major areas found.



- INDOT pumping to the northeast interchange infield at County Line Rd
- Water must have been subsiding since debris was out into the travel lanes



• Pipe under County Line Road potentially backing up into northeast infield and median



- At arrival, infield water elevation approximately 830 feet. Higher prior.
- Median Casting Elevation 830.5 feet. Edge of road around 831-832 feet.



Possible Causes

• Tailwater channel downstream of culvert was flat, restricted and heavily vegetated.

- Culvert capacity
- Median pipe inverts too low for high tailwater conditions
- Clogging (inlet was submerged and couldn't be seen)
- No flanking inlets in the sag for redundancy
- Snow melt the day before

- Between County Line Road & Southport Road
- Multiple sag areas, small drainage areas
- Flooded, but not into lanes Where did all the grass come from?





Possible Causes

- Clogging
- No flanking inlets in the sags for redundancy
- In one location there were dual inlets (pre-construction), now a single inlet

- Just north of Southport Road at Little Buck Creek
- Inlet submerged, berm (higher than road) at the creek
- Was flooded into travel lanes before arrival



Possible Causes

• Long stretch of drainage area, high discharge if at grade inlets are clogged

NextLevel

- Main inlet not found, either submerged, clogged, or under riprap
- Berm higher than road, flow couldn't get into the creek
- Flow had to go into the roadway instead
- No flanking inlet for redundancy
- Possibly high tailwater condition

- Between Southport Road and I-465 (Near Edgewood Ave)
- Inlet submerged
- Was flooded across most of the travel lanes (overtopping the road crown)







- Maintenance crews started pumping water with limited results
- INDOT Hydraulics found sag inlet after searching in water for 30 minutes
- After somewhat unclogging, water level started dropping immediately



- Most of the water was gone within 10 minutes
- Even a N-12 inlet can clog







• Google Street View June 2019



Possible Causes

• Long stretch of drainage area (0.8 miles long)

- Clogging
- No flanking inlet for redundancy

- Near area #4, Downstream of Median to Median pipe
- Trash debris trapped within the outlet grate



I-65 South Indy Example – Recommendations

All Areas

- Routine maintenance to clean debris
- Provide flanking inlets to improve redundancy

Area 1

• Enlarge downstream ditch capacity and bore a new pipe under County Line Road

Area 3

Lower ditch berm below road shoulder elevation



I-65 South Indy Example – Applications

INDOT Road Cleaning Program

- INDOT has started contracting out trash and litter pickup
- INDOT crews still pickup trash as well
- In Fall 2018, 2339 40-gallon bags of trash were filled along Marion County interstates with 749 man hours
- In April 2019, 3825 40-gallon bags were filled on I-64 and 4170 bags were filled on I-69 from Monroe to Vanderburgh County





I-65 South Indy Example

Storm Event

- Snowmelt the day before
- 2.6 inches recorded at airport
- 2-3 inches per radar estimate
- Estimated 3-6 hour storm duration (per Weather Underground)

30-

Appears to be 5 to 10-year storm event (per NOAA Atlas 14)

		FD3-baseu	precipitation	rnequency	estimates w		
ation	Average recurrence interval (years)						
	1	2	5	10	25	50	Ē
nin	0.376 (0.336-0.424)	0.448 (0.399-0.504)	0.536 (0.477-0.603)	0.606 (0.538-0.681)	0.697 (0.614-0.785)	0.768 (0.672-0.867)	ĺ
min	0.584 (0.522-0.659)	0.699 (0.623-0.787)	0.833 (0.742-0.938)	0.936 (0.830-1.05)	1.07 (0.939-1.20)	1.16 (1.02-1.31)	
min	0.716 (0.639-0.808)	0.855 (0.762-0.963)	1.02 (0.911-1.15)	1.15 (1.02-1.29)	1.32 (1.16-1.48)	1.44 (1.26-1.63)	[
min	0.948 (0.846-1.07)	1.14 (1.02-1.29)	1.40 (1.25-1.58)	1.60 (1.42-1.80)	1.86 (1.64-2.09)	2.06 (1.80-2.33)	
min	1.16 (1.03-1.31)	1.40 (1.25-1.58)	1.76 (1.57-1.98)	2.03 (1.80-2.29)	2.41 (2.12-2.72)	2.71 (2.37-3.06)	
hr	1.35 (1.21-1.53)	1.64 (1.46-1.85)	2.06 (1.84-2.32)	2.40 (2.13-2.70)	2.87 (2.53-3.22)	3.26 (2.85-3.66)	[
hr	1.43 (1.29-1.62)	1.74 (1.55-1.96)	2.19 (1.95-2.47)	2.55 (2.27-2.87)	3.07 (2.70-3.45)	3.50 (3.05-3.93)	
hr	1.70 (1.52-1.93)	2.06 (1.84-2.33)	2.60 (2.32-2.93)	3.04 (2.69-3.42)	3.67 (3.22-4.12)	4.20 (3.65-4.71)	

PDS-based precipitation frequency estimates with 90% cont

GUIDANCE

- INDOT has very limited hydraulic guidance for median drains in the Indiana Design Manual (IDM)
- INDOT has learned from previous added travel lane (ATL) projects
- The following guidance is mostly based on the most recent ATL project technical provisions
- IDM to be updated with median drain policy in the near future

Use P-12 inlets (IDM 203-4.04(12))

• Recommend using N-12 inlets if at all possible, to fit within the design footprint



Inlet Spacing and HGL calculations (from recent ATL technical provisions)

- Use 50-year storm event
 - For median ditch spread
 - For HGL check on median inlet and pipe capacity
- Should not encroach into travel lanes (0 freeboard allowed for median but <u>more</u> is desired)
 - Provide some freeboard when possible
 - Example upgrade a 15" pipe to 18" for some redundancy if near 0 freeboard
- No stormwater detention allowed in the median ditches



Flanking Inlets Required at all Sags

- Should be set below low sag edge of travel lane
- For one direction flow to sag, one flanker inlet is sufficient



For outlet into a pond, near a culvert/bridge or the side ditch is part of a defined creek/stream

- Check to see if median pipe outlet invert will be below Q100 Elevation
- If so, check HGL (with appropriate tailwater depth) to make sure it is not above Edge of Travel Lanes



EXAMPLE: Since Q100 Elev > Median Invert Elev, additional HGL check required



For outlet into typical side ditch

- If median pipe outlet invert is set 1.0 feet above ditch flowline or higher
 - No further action required
- If median pipe outlet invert is set 0.5 feet to 1.0 feet above ditch flowline
 - HGL check required with appropriate side ditch water elevation
- Median pipe outlet invert less than 0.5 feet above ditch flowline NOT ALLOWED



For outlet into typical side ditch

- If median pipe outlet invert is set 1.0 feet above ditch flowline or higher
 - No further action required
- If median pipe outlet invert is set 0.5 feet to 1.0 feet above ditch flowline
 - HGL check required with appropriate side ditch water elevation
- Median pipe outlet invert less than 0.5 feet above ditch flowline NOT ALLOWED



Runoff Coefficient "C" for Rational Method

- Pavement
 - No less than 0.90
- Recycled Asphalt Pavement (RAP) or compacted No. 53 Stone
 - No less than 0.80

Manning's Channel Roughness "n" Value

- Pavement
 - Minimal 0.012
- Recycled Asphalt Pavement (RAP) or compacted No. 53 Stone
 - Minimal 0.025



Include a spreadsheet to compare elevations - show HGL, ETL, Rim, Inverts, Tailwater Elev, Flowline Elev, Pipe size

Image: base base base base base base base base	L < ETL Outlet
Image: heat of the state o	Velocity
Up Down Up Down Up Down Up Down Up Down HGL HGL₀ HGL₀<	Y/N (fps)
Median Outlets Image: Constraint of the system of the	
2414+85 Med. Rt. 455 OUT 69 15 1.25 0.77 0.012 594.17 593.64 594.89 594.89 572.93 5.82 595.90 594.89 596.67 597.64 2435+00 Med. Lt. 456 OUT 70 15 1.25 0.94 0.012 581.66 581.00 582.91 582.25 574.37 6.72 583.67 582.25 585.10 585.10 585.10 582.91 582.91 580.96 571.08 10.57 583.21 580.96 583.23 584.12 584.12 584.12 584.12 584.12 584.12 584.12 583.21 580.96 571.08 10.57 583.21 580.96 583.23 584.12 58	
2435+00 Med. Lt. 456 OUT 70 15 1.25 0.94 0.012 581.66 581.00 582.25 582.25 574.37 6.72 583.67 582.25 584.15 585.10 2439+23 Med. Lt. 458 OUT 73 18 1.50 1.85 0.012 580.81 579.46 580.96 580.96 571.08 10.57 583.21 580.96 583.23 584.12	Y 5.69
2439+23 Med. Lt. 458 OUT 73 18 1.50 1.85 0.012 580.81 579.46 582.31 580.96 580.96 571.08 10.57 583.21 580.96 583.23 584.12	Y 6.30
	Y 9.43
2442+00 Med. Lt. 461 OUT 73 15 1.25 1.55 0.012 581.30 580.17 582.55 581.42 581.42 574.81 5.98 583.07 581.42 583.79 584.46	Y 5.76
2446+50 Med. Lt. 462 OUT 71 15 1.25 1.66 0.012 582.19 581.01 583.44 582.26 582.26 573.89 5.98 583.96 582.26 584.68 585.37	Y 5.76
2450+00 Med. Lt. 463 OUT 71 15 1.25 1.52 0.012 582.90 581.82 584.15 583.07 583.07 572.41 5.98 584.67 583.07 585.39 586.11	Y 5.76
2454+00 Med. Lt. 464 OUT 71 15 1.25 1.51 0.012 583.68 582.61 584.93 583.86 583.86 572.98 5.98 585.45 583.86 586.18 586.99	Y 5.76
2458+00 Med. Lt. 465 OUT 69 15 1.25 1.51 0.012 584.47 583.43 585.72 584.68 584.68 572.64 6.47 586.40 584.68 586.96 587.84	Y 7.70
2466+30 Med. Lt. 466 OUT 72 15 1.25 1.88 0.012 585.97 584.62 587.22 585.87 585.87 574.63 5.90 587.71 585.87 588.47 589.45	Y 5.72
2470+00 Med. Lt. 468 OUT 73 15 1.25 0.79 0.012 586.69 586.11 587.94 587.36 587.36 574.45 5.24 588.25 587.36 589.20 590.18	Y 5.70
2481+30 Med. Lt. 470 OUT 81 15 1.25 1.54 0.012 586.71 585.46 587.96 586.71 586.71 574.75 5.49 588.34 586.71 589.11 590.19	Y 5.52
2488+00 Med. Lt. 471 OUT 92 15 1.25 1.71 0.012 584.24 582.67 585.49 583.92 583.92 579.86 6.39 586.14 583.92 586.75 587.74	Y 5.98
2491+80 Med. Rt. 473 OUT 85 15 1.25 1.69 0.012 582.86 581.42 584.11 582.67 582.67 579.81 6.88 584.93 582.67 585.19 586.18	Y 8.17
2496+72 Med. Lt. 476 OUT 77 18 1.50 0.74 0.012 580.63 580.06 582.13 581.56 581.56 579.00 9.67 582.81 581.56 583.38 584.30	Y 5.47
2499+00 Med. Rt. 478 OUT 117 15 1.25 1.71 0.012 581.93 579.93 583.18 581.18 581.18 577.31 6.80 583.97 581.18 584.26 585.16	Y 6.21
2503+50 Med. Lt. 479 OUT 82 15 1.25 1.71 0.012 588.58 587.18 589.83 588.43 588.43 578.57 6.80 590.62 588.43 591.09 592.08	Y 8.17
2508+00 Med. Lt. 480 OUT 83 15 1.25 1.64 0.012 600.63 599.27 601.88 600.52 600.52 581.41 6.47 602.56 600.52 603.12 604.02	Y 6.02
2520+00 Med. Lt. 481 OUT 71 15 1.25 1.82 0.012 600.45 599.16 601.70 600.41 600.41 579.99 6.55 602.40 600.41 602.96 603.95	Y 6.07
2524+80 Med. Lt. 483 OUT 69 15 1.25 1.51 0.012 588.74 587.70 589.99 588.95 579.15 7.46 591.03 588.95 591.25 592.24	Y 7.86
2530+04 Med. Lt. 485 OUT 77 15 1.25 1.75 0.012 583.74 582.39 584.99 583.64 583.64 580.78 8.68 586.55 583.64 586.52 587.42	Y 8.58







